

MARYSVILLE FIRE DIVISION FIRE INSPECTION REPORT



Inspection and Compliance Orders								
Facility:	St. Johns Lutheran School	Address:	12809 State Route 736 #					
Phone:	937-644-5540	Address.						
Fax:		City:	Marysville					
Email:		State:	Ohio	Postal Code:	43040			
Primary Contact								
Contact:	Wagner, Joe	Work:	614-561-8685					
Email:	jwagner@sjsmarysville.org	Cell:	937-644-0866					

Inspection Type: General Inspection

Violation Code	Days to Correct*	Violation	Notes	Location
				

Inspection Notes:

Add address to front of building so its visible from the road at least 4 inches tall and contrasting colors. Exit light needs repaired above the stairs by the lab. Extinguisher in mobile trailer needs to be on bracket. Room 15 and 16 needs exit sign repaired so battery backup works. Keep an eye on storage height as it shall be 24 inches below the ceiling. Egress light hallway by bathrooms need repaired so battery backup works. Re-inspect March 11, 2024 All violation's have been fixed. Thank you and see you next yea!!



^{*} Number of days to correct from date inspected.

A variance procedure is available. Please contact the inspector named for further assistance with this or any other matter.