


UNION COUNTY SCHOOL ENVIRONMENT INSPECTION FORM

Facility Name: St John's	Address: 12809 SR, 736, Marysville, OH 43040
Superintendent:	Address:
Principal: Richard Rausch	Address: rrausch@sjsmarysville.org
Maintenance: Joe Wagner	Address: jwagner@sjsmarysville.org

(Y)	(N)		(Y)	(N)	
Surroundings			Toilet and Locker Room Facilities		
		Location			Cleaning, repair & adequacy - Rooms
		Grounds, walkway, and driveways			Cleaning, repair & adequacy - Showers & toilet fixtures
Building					Cleaning, repair & adequacy - Lockers & modesty equipment
		Structure			Cleaning, repair & adequacy - Hand washing facilities
		Floor cleaning & repair			Ventilation
		Walls & ceilings— cleaning & repair			Rest room supplies
		Doors & windows	Waste Disposal System		
Heating & ventilation					Sewage system operation & maintenance
		Thermostat & thermometer— Each classroom			Refuse & garbage disposal & storage
		Temperature & humidity	School Room Facilities		
X		Ventilation & dust control			Adequate equipment & furnishings
Lighting					Maintenance of equipment & furnishings
		Adequate artificial lighting			Room population (overcrowding)
		Maintenance of fixtures	Playground Safety		
		Quality and proper use of lighting			Adequate protective surfacing – Minimum twelve (12) inches deep
Water Supply					Adequate fall zone – Minimum six (6) feet
		Source development & treatment			No protrusion and entanglement hazards
		Pressure & chemical quality			No entrapment hazards
		Plumbing, maintenance and design			Sufficient equipment spacing – Minimum twelve (12) feet
		Drinking fountains			No trip hazards
					Sufficient supervision
Accident Prevention					Age appropriate activities / equipment
		Traffic safety			Maintenance
		Fire exits marked, adequate			No pinch, crush, shearing, or sharp edge hazards
		Firefighting equipment			Guardrails on platforms
		Rooms & halls free of hazards			No improper equipment for a playground – No heavy animal swings, multiple occupancy swings, free swinging ropes, exercise rings, or trapeze bars.
		Stairways and playgrounds free of hazards	Insect control		
		Properly equipped emergency room			No evidence of insect or rodent infestation
					Proper control procedures used

REMARKS:
Ceiling vent in the cafeteria/gym end hallway needs to be dusted/cleaned.

Signature: 	Date of inspection: October 25, 2022
--	--------------------------------------